

13	PF FR C/PORCA PO	5/16 X 3/4	10,12
14	PF FR C/PORCA PO	5/16 X 1.	13,04
30	PF FR C/PORCA PO	3/8 X 1.1/4	20,51
4.698	PORCA SX C.8 BC	MA 8.	3,92
4.700	PORCA SX C.8 BC	MA 12.	14,99
9.083	PF CORREIA C/P PO (CAB.28)	5/16 X 2.	33,96
21.443	BARRA ROSCADA ZB	MA 16.	8,37
21.949	PORCA SX ZB - CH.3/4	NC 1/2	10,51
22.000	PORCA SX ZB	MA 6.	1,85
22.002	PORCA SX ZB	MA 8.	3,83
22.003	PORCA SX ZB	MA 10.	7,39
22.004	PORCA SX ZB	MA 12.	12,49
22.461	PF SX MA 933 ZB	6. X 16.	5,71
22.463	PF SX MA 933 ZB	6. X 20.	5,26
22.465	PF SX MA 933 ZB	6. X 25.	5,01
22.467	PF SX MA 933 ZB	6. X 30.	5,45
22.474	PF SX MA 933 ZB	8. X 16.	9,48
22.476	PF SX MA 933 ZB	8. X 20.	10,00
22.480	PF SX MA 933 ZB	8. X 30.	10,56
22.505	PF SX MA 933 ZB	10. X 20.	15,75
22.507	PF SX MA 933 ZB	10. X 25.	16,58
22.509	PF SX MA 933 ZB	10. X 30.	17,80
22.535	PF SX MA 933 ZB	12. X 30.	24,38
23.185	PF SX MA 933 ZB	10. X 60.	26,13
42.056	PF SX MA 933 8.8 BC	8. X 20.	10,15
42.113	PF SX MA 933 8.8 BC	12. X 30.	35,87

42.114	PF SX MA 933 8.8 BC	12. X 35.	38,73
42.461	PF SX MA 933 BC	6. X 16.	4,88
42.474	PF SX MA 933 BC	8. X 16.	8,10