

1.087	PF FR MA 8.8 BC	6. X 16.	6,72
20.229	PF SX NC ZB	1/4 X 1.1/4 RI	5,47
20.239	PF SX NC ZB	5/16 X 3/4 RI	8,13
20.241	PF SX NC ZB	5/16 X 1. RI	8,68
20.258	PF SX NC ZB	3/8 X 1. RI	10,74
21.087	PF FR MA 8.8 ZB	6. X 16.	7,04
21.097	PF SX NC ZB	3/8 X 3/4 RI	13,00
21.945	PORCA SX ZB - CH.7/16	NC 1/4	1,88
21.946	PORCA SX ZB - CH.1/2	NC 5/16	2,76
21.947	PORCA SX ZB - CH.9/16	NC 3/8	3,85
21.949	PORCA SX ZB - CH.3/4	NC 1/2	8,27
22.000	PORCA SX ZB	MA 6.	1,62
22.461	PF SX MA 933 ZB	6. X 16.	4,35
22.465	PF SX MA 933 ZB	6. X 25.	4,97
22.467	PF SX MA 933 ZB	6. X 30.	7,26
22.970	PF SX MA 933 8.8 ZB	6. X 16.	3,60
30.001	PF A-AT PAN FS ZB	2,9 X 6,5	0,63
30.218	PF A-AT PAN FP ZB	2,9 X 6,5	0,81
30.434	PF MAQ CIL FS BC	8. X 16	6,78
30.452	PF MAQ RED FS ZB	5/32 X 7/8	1,59
30.453	PF MAQ RED FS ZB	5/32 X 1.	2,30
30.455	PF MAQ RED FS ZB	5/32 X 1.1/2	2,95
31.602	PF A-AT PAN F.COMBINADA ZB	2,9 X 13	1,12